

## Message Text

UNCLASSIFIED

PAGE 01 LAGOS 10498 141507Z

53

ACTION SY-04

INFO OCT-01 AF-10 ISO-00 /015 W  
----- 106707

R 140955Z NOV 74

FM AMEMBASSY LAGOS

TO AMEMBASSY ABIDJAN

INFO SECSTATE WASHDC 6813

UNCLAS LAGOS 10498

ABIDJAN FOR TSO

WASHDC FOR A/SY/T

E.O. 11652: N/A

TAGS: ASEC

SUBJECT: REPAIR ON MK II INCENERATOR

MOTOR ON MODEL II INCINERATOR HAS BURNED OUT. LOCAL ESTIMATE  
TO HAVE MOTOR REWOUND IS DOLS.65.00. NO GUARANTEE ON LOCAL WORK,  
QUALITY OF WHICH QUESTIONABLE. IF POSSIBLE, WOULD LIKE  
TO HAVE A NEW MOTOR SENT TO THIS POST. PLEASE ADVISE.  
REINHARDT

UNCLASSIFIED

NNN

## Message Attributes

**Automatic Decaptioning:** X  
**Capture Date:** 01 JAN 1994  
**Channel Indicators:** n/a  
**Current Classification:** UNCLASSIFIED  
**Concepts:** n/a  
**Control Number:** n/a  
**Copy:** SINGLE  
**Draft Date:** 14 NOV 1974  
**Decaption Date:** 01 JAN 1960  
**Decaption Note:**  
**Disposition Action:** n/a  
**Disposition Approved on Date:**  
**Disposition Authority:** n/a  
**Disposition Case Number:** n/a  
**Disposition Comment:**  
**Disposition Date:** 01 JAN 1960  
**Disposition Event:**  
**Disposition History:** n/a  
**Disposition Reason:**  
**Disposition Remarks:**  
**Document Number:** 1974LAGOS10498  
**Document Source:** CORE  
**Document Unique ID:** 00  
**Drafter:** n/a  
**Enclosure:** n/a  
**Executive Order:** N/A  
**Errors:** N/A  
**Film Number:** D740328-1119  
**From:** LAGOS  
**Handling Restrictions:** n/a  
**Image Path:**  
**ISecure:** 1  
**Legacy Key:** link1974/newtext/t19741144/aaaabkzo.tel  
**Line Count:** 38  
**Locator:** TEXT ON-LINE, ON MICROFILM  
**Office:** ACTION SY  
**Original Classification:** UNCLASSIFIED  
**Original Handling Restrictions:** n/a  
**Original Previous Classification:** n/a  
**Original Previous Handling Restrictions:** n/a  
**Page Count:** 1  
**Previous Channel Indicators:** n/a  
**Previous Classification:** n/a  
**Previous Handling Restrictions:** n/a  
**Reference:** n/a  
**Review Action:** RELEASED, APPROVED  
**Review Authority:** golinofr  
**Review Comment:** n/a  
**Review Content Flags:**  
**Review Date:** 28 OCT 2002  
**Review Event:**  
**Review Exemptions:** n/a  
**Review History:** RELEASED <28 OCT 2002 by maustmc>; APPROVED <29-Oct-2002 by golinofr>  
**Review Markings:**

Declassified/Released  
US Department of State  
EO Systematic Review  
30 JUN 2005

**Review Media Identifier:**  
**Review Referrals:** n/a  
**Review Release Date:** n/a  
**Review Release Event:** n/a  
**Review Transfer Date:**  
**Review Withdrawn Fields:** n/a  
**Secure:** OPEN  
**Status:** NATIVE  
**Subject:** REPAIR ON MK II INCENERATOR MOTOR ON MODEL II INCINERATOR HAS BURNED OUT. LOCAL ESTIMATE  
**TAGS:** ASEC  
**To:** ABIDJAN  
**Type:** TE  
**Markings:** Declassified/Released US Department of State EO Systematic Review 30 JUN 2005